ROCKY FLATS PLANT EMD OPERATING PROCEDURES MANUAL Manual No.: Procedure No.: 5-21000-OPS-GT Table of Contents, Rev 4

1 of 2

Page: Effective Date:

11/01/91

Organization:

Environmental Management

THIS IS ONE VOLUME OF A SIX VOLUME SET WHICH INCLUDES:

VOLUME I: FIELD OPERATIONS (FO)
VOLUME II: GROUNDWATER (GW)
This is aVOLUME III: GEOTECHNICAL (GT)

CONTROLLED DOCUMENT SURFACE WATER (SW)

EG&G - ROCKY FATS & WOLUME VI: AIR (AP)

ENVIRONMENTAL MADE TO

The

April 1

TABLE OF CONTENTS
FOR VOLUME III: GEOTECHNICAL

New Proc. <u>No</u> .	Old Proc. <u>No.</u>	Title	Rev. <u>No.</u>	Effective <u>Date</u>
GT.01	3.1	Logging Alluvial and Bedrock Material	1	8/30/91
GT.02	3.2	Drilling and Sampling Using Hollow Stem Auger Techniques	1	8/30/91
DCN 91.01		Unconsolidated core samples need not be peeled before sampling	1	10/29/91
GT.03	3.3	Isolating Bedrock From the Alluvium with Grouted Surface Casing	1	8/30/91
DCN 91.01		Change in criteria for cement grouting	1	10/02/91
DCN 91.02		Grout procedure clarification	1	10/28/91
GT.04	3.4	Rotary Drilling and Rock Coring	1	8/30/91
DCN 91.01		Core barrel decontamination	1	10/22/91
DCN 91.02		Clarification of measuring tape decontamination requirements	1	10/29/91
GT.05	3.5	Plugging and Abandonment of Boreholes	1	8/30/91
DCN 91.01		Surface casing classification	1	10/22/91

DOCUMENT CLASSIFICATION REVIEW WAIVER PER CLASSIFICATION OFFICE

ADMIN RECORD

A-SW-000944

ROCKY FLATS PLANT EMD OPERATING PROCEDURES MANUAL

Manual No.: Procedure No.: Page: 5-21000-OPS-GT Table of Contents, Rev 4 2 of 2

Effective Date:

11/01/91

Organization:

Environmental Management

New Proc. <u>No.</u>	Old Proc. No.	<u> Title</u>	Rev. <u>No.</u>	Effective <u>Date</u>
GT.06	3.6	Monitoring Wells and Piezometer Installation	1	8/30/91
DCN 91.01		Industry Standard is 1 foot into Bedrock	1	10/15/91
DCN 91.02		For the Sitewide Program, Claystone Smearing does not seem to be a problem	1	10/15/91
GT.07	3.7	Logging and Sampling of Test Pits and Trenches	1	8/30/91
GT.08	3.8	Surface Soil Sampling	1	8/30/91
GT.09	3.9	Soil Gas Sampling and Field Analysis	1	8/30/91
GT.10	3.10	Borehole Clearing	1	8/30/91
GT.11	3.11	Plugging and Abandonment of Wells	1	8/30/91
GT.15	3.15	Geophysical Borehole Logging	1	8/30/91
DCN 91.01		No Hole will be left Unlogged at the end of the day	1	10/15/91
GT.17	3.17	Land Surveying	1	8/30/91
GT.18	3.18	Surface Geophysical Surveys	1	8/30/91
GT.19	3.19	Field Gas Chromatographs	1	8/30/91
GT.20	3.20	Procedures for Soil Interstitial Water Sampling and Sampler Installation	1	8/30/91

ENVIRONMENTAL MANAGEMENT DOCUMENT CHANGE NOTICE (DCN)

CONTROLLED DOCUMENT

rocedure Number 5-21000-OPS-GT.4, Rev. 1

Page 1 of 1

					- Em	EG&G — ROCK	Y FLATS PLANT			
Title						Date	"	OCN Num	ber DPS-GT.4	
		nd Rock Corin	g			This is 12	28 Stamp	9	1.02	
Expires _	1-30-	91		Pro	ocedure Rev	ision Required	X Yes No			
Scope Lin	nitation	Sitewide Geol	logic							
item		Step or	<u> </u>	Changes						
Number	Page	Paragraph		(Use DCN CONTINUATION SHEET for Additional Space)						
1	8 of 10	6.0 paragraph 1	circula	ating me runs.	edium, no de	contamination of m	n: "When coring bed easuring tapes is n contaminated after o	ecessary	between	
The poten	tially cor	taminated allu	uvium t	as alrea	ady been iso	ference Correspond lated from the bedra ling fluid, the expos	ding Items Above) ock. In addition, the	e borehol e measuri	e is filled with ng tape.	
Concurr	ence	Organizati	on	Req	Date	Concurrence	Organization	Req	Date	
Jany M.	Inny	QAPM		X	10/29/41	at Primos	User	X	10/28/91	
		nsible Manage ชาวน์	er	Date	9/9/	Is Posting Reqd? X Yes No	If Yes, By What D	ate?	Date Posted	